










SACE Tmax XT

Motore M e Contatto di segnalazione molle cariche S33 M/2 - XT7M
Motor M and Contact for signalling springs loaded S33 M/2 - XT7M
Motor M und Meldekontakt Federn gespannt S33 M/2 - XT7M
Moteur M et Contact de signalisation ressorts bandes S33 M/2 - XT7M
Motor M y Contacto de señalización resortes cargatos S33 M/2 - XT7M
电机M和加载弹簧信号触点 S33 M/2 - XT7M

XT7M




	A	B	C	D
				
 MOTOR M	1	2	1	
 S33 M/2			1	1




3

F




4



F




5



F










95	35		R1	V3	Vn	Ge+	Szi	Ne-	24Vdc ONLY	K2	W4					45	D1	C1	C11	11	21	31	41					
96	36	U1	R1	V2	Rct	Ge-	Szo	Ne+		K1	W3						46		C3	C13	12	22	32	42				
98	38	U2		V1	Gzo	Szc	Gzi	Rca									48	D2	C2	C12	14	24	34	44				
	S33	M		Trip Unit I/O				EKIP Supply				Module				Module				RTC	YU	YO?	YC	YO	Q1	Q2	Q3	Q4









13



W





14

W







95	35	15	37	47	V3	Vn	Ge+	Szi				Ne-	45	25	D1	C1	C11	11	21	31	41
33	36	U1	38	48	V2	Rct	Ge-	Szo				Ne+	46	26		C3	C13	12	22	32	42
96	38	U2			V1	Gzo	Szc	Gzi				Rca	48	28	D2	C2	C12	14	24	34	44
S51	SY	S4/1	S4/2		Trip Unit I/O				Module	Module	EKIP Supply	TU I/O	RTC	S52	YU	YC	YO	Q1	Q2	Q3	Q4

